**Bulletin-Axle Info** 

## Genuine Spicer® R155/156 Produced Before February 2016 - Spacer Discontinuation - Part Number Information

Date: August 6, 2019

To: All Dana Aftermarket Group Spicer® Heavy Axle Customers

Affected Models: R155/R156 Models produced before February 15, 2016

The R155 and R156 drive axle model produced before February 15, 2016 went through a pinion bearing design change to improve efficiency. This change in design impacted the stack up of the pinion bearings and spacer. The spacer thickness was increased which made the two generations of spacers incompatible. The pinion bearing spacers related to this "early model" will no longer be available in service.

When servicing "early model" carriers you must make sure the pinion bearings and spacers are from the same generations, new with new, old with old.

The spacers discontinued are in table 1 below. The new spacers and new pinion bearing cones are in table 2.

Table 1 - OLD

Part-No.	Description
134503	Spacer-Pinion
134506	Spacer-Pinion
134507	Spacer-Pinion
134513	Spacer-Pinion
134514	Spacer-Pinion
134515	Spacer-Pinion
134516	Spacer-Pinion
134517	Spacer-Pinion
134520	Spacer-Pinion
134521	Spacer-Pinion
134522	Spacer-Pinion
134523	Spacer-Pinion
134524	Spacer-Pinion
134538	Spacer-Pinion

Table 2 - NEW

Part-No.	Description
504329	Pinion Bearing Spacer Kit
10021815	Pinion Bearing Cone - Inner
10021816	Pinion Bearing Cup - Inner
10032378	Pinion Bearing Cone - Outer
10032379	Pinion Bearing Cup - Outer

If you need additional information, please contact your Dana Aftermarket representative. Thank you for your continued support of Dana Aftermarket products!

Courtney Melin

**Courtney McGuire** 

Associate Product Manager Spicer® Heavy Axle Products

SpicerParts.com/Performance

Dana Aftermarket Group

PO Box 1000 Maumee, Ohio 43537 Warehouse Distributors: 1.800.621.8084 OE Dealers: 1.877.777.5360