

Bulletin-Axle Info

Genuine Spicer® R155/156 Produced Before February 2016 - Pinion Shim Discontinuation

Date: Monday, August 26, 2019

To: All Dana Aftermarket Group Spicer® Heavy Axle Customers

Affected Models: R155/R156 Models produced before February 15, 2016

The R155 and R156 drive axle models produced before February 15, 2016 went through a pinion bearing design change to improve efficiency. This change in design impacted the stack up of the pinion bearings and shims. The shim thickness was increased, making the two generations incompatible. The pinion bearing shims related to this "early model" will no longer be available in service.

When servicing "early model" carriers you must make sure the pinion bearings, spacers, and shims are from the same generation, new with new, old with old. Please also reference HAXL-PNI-110 on the spacer discontinuation.

The shims in Table 1 on the right will be discontinued when stock is exhausted. The new shims, pinion bearing cups, and cones are in Table 2.

If you need additional information, please contact your Dana Aftermarket representative. Thank you for your continued support of Dana Aftermarket products!

Table 1 - OLD

Table 1 - OLD		
Description		
Pinion Bearing Shim		

Table 2 - NEW

Part-No.	Description
504363	Pinion Bearing Shim Kit
10021815	Pinion Bearing Cone - Inner
10021816	Pinion Bearing Cup - Inner
10032378	Pinion Bearing Cone - Outer
10032379	Pinion Bearing Cup - Outer

Coursey Medin

Courtney McGuire

Associate Product Manager Spicer® Heavy Axle Products

Dana Aftermarket GroupPO Box 1000 Maumee, Ohio 43537
Warehouse Distributors: 1.800.621.8084
OE Dealers: 1.877.777.5360